


Parts book  
For High Speed Overlock Machines

***Tre 04 DD***  
***Tre Orlo 15 DD***  
***Quattro 24 DD***  
***Cinque 35 DD***


 ***texi***




# 1




2



# 3



# 4







5

G

Please confirm the correct part by the gauge parts lists.




# 6 **G** Please confirm the correct part by the gauge parts lists.





# 7 **G** Please confirm the correct part by the gauge parts lists.



● 5 threads



8




Please confirm the correct part by the gauge parts lists.




**9**



Please confirm the correct part by the gauge parts lists.




# 10 **G** Please confirm the correct part by the gauge parts lists.



11

G

Please confirm the correct part by the gauge parts lists.






# 12


## G

Please confirm the correct part by the gauge parts lists.






# 13




# 14




Please confirm the correct part by the gauge parts lists.







# 15



# 16




# 17




# 18



Please confirm the correct part by the gauge parts lists.






● 5 threads






# 19




# 20

● 5 threads




# 21

(Blind hemming)



(Attaching tape)




# 22


- 3 threads  
10008015
- 4 threads  
10007906

- 5 threads  
10004956

**SET UP INSTRUCTIONS**




# 23



24


**G**

Please confirm the correct part by the gauge parts lists.







# 25

















# 26



# 27



GAUGE PARTS LIST

	<b>Model</b>													
	Tre 04 DD	10009578	10033777	10003209	10003208	10033778	10002849	10004564	10009609	10009516	10009611	10010866	10009313	10009517
	Tre Orlo 15 DD	10013122	10013121	10006250	10006251	10013120	10002849	10004337	10009609	10009516	10009611	10010866	10009313	10009517
	Quattro 24 DD	10013136	10033777	10003209	10003208	10033778	10004345	10005977	10011061	10009516	10009611	10010866	10009313	10009517
	Cinque 35 DD	10010549	10033781	10004166	1004167	10033782	10033780	-	10009403	10009516	10009611	10009765	10009313	10009517













